


# HEAT ON TRANSFERLOGO MANUAL

## LP272




15 x 15 cm  
1-2 Kg/Bar

15 x 38 cm  
4-5 Kg/Bar

40x40 cm  
5-6 Kg/Bar

**1.**

Recommended pressure for LOXY transfers.




150-160°C/302-320°F

<3 sec

**2.**

Pre-heat the fabric up to 3 seconds to remove residues, impurity and reduce shrinkage.




150-160°C/302-320°F

12 sec

**3.**


Apply the transfer, with the film facing upwards.



>10 sec

**4.**


Wait minimum 10 seconds before removing the film. Some fabrics require full cooldown.



150-160°C/302-320°F

<3 sec

Some fabrics may require additional press. Use backside of the folie over the transfer.



48 hours

The print has to rest 48 hours before starting washing procedure.

*The above general recommended applications parameters must be tested and internally verified for different fabrics and applications. Some fabrics may require additional or deviating procedures.*

PRINTED IN NORWAY

2021-8

LOXY® Print